

Template showing where to drill the hole in the TD5 bellhousing to hold the converter bolts when fitting the TD5 heavy duty torque converter

